

Engine system service required

Here is what I did after many months of the "Engine System Service Required" message. It would come and go. After a while it would just stay on and not disappear. I read something somewhere that if you take the oil filler cap off and start the engine with it off

No problems (except a couple squeaks) until Friday evening when this popped up when the ignition was turned on: "Propulsion system: Service required." It had been driven on multiple short trips earlier in the day.

Causes of Volvo Engine System Service Required Message. When you see the "Engine System Service Required" message on your Volvo, it's important to understand the underlying reasons. In this section, you'll learn about some common issues that can trigger this message and what you can do to resolve them.

The message "Engine System Service Urgent" occasionally comes up. At the same time, my Volvo XC90 loses speed and can't drive over 50mph. I thought it was to do with service, so I serviced my car last week but the message comes back.

A few days ago had the engine system service required light come on and I can't get it to go away. I have tried the odometer button reset that generally works. My closest Volvo dealer is almost 2 hours away through the mountains.

I bought a brand new 2022 XC90 extended range back in Apr 2022 at Volvo SF. Today I got the check engine on with "propulsion system service required." Tonight I'm getting notification that the car stopped charging. I'm charging it directly into an 110V outlet

Web: <https://billyprim.eu>

Chat online: <https://tawk.to/chat/667676879d7f358570d23f9d/1i0vbu11i?web=https://billyprim.eu>